960482 PRINTED: 08/05/2015

Division of Health Service Regulation (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION (X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES COMPLETED IDENTIFICATION NUMBER: A. BUILDING: 01 AND PLAN OF CORRECTION 05/07/2015 R. WING FCL045114 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 1310 HEBRON STREET WILLOW SPRINGS ASSISTED LIVING # 2 HENDERSONVILLE, NC 28739 PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (EACH CORRECTIVE ACTION SHOULD BE PREFIX (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL CROSS-REFERENCED TO THE APPROPRIATE DATE PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) TAG DEFICIENCY) TAG C 000 C 000 Initial Comments Report of Biennial Construction Survey by Frank Strickland on 05/07/2015: Based on Information gathered from DHSR database, this facility was either first licensed or submitted on 12/28/2011 as a Family Care Home. The Facility is currently licensed for six Ambulatory Residents. Therefore, this facility was surveyed for conformance with the 2005 " CONSTRUCTION SECTION regulations for family care homes " ., and the 2009 Edition of the North Carolina State Building Code Section 421.2. Deficiencies were cited and a Plan of Correction Replaced 4/26% This is required. C 135 C 135 Bathroom-Hand Grips SECTION .0300 - THE BUILDING wagnt stable. So we mirewit it 10A NCAC 13G .0309 BATHROOM (e) Hand grips shall be installed at all commodes, tubs and showers used by the residents. where the Audi where This Rule is not met as evidenced by: 1-Based on observation, the facility has not maintained the hand grips in the Bathrooms. in the unil. This will effect all residents using commodes, President's state much tubs and showers. Findings on 05/07/2015 The hand grips are not supported properly in the shower surrounding walls for the Bathroom that is located adjacent to Room 1. Division of Health Service Regulation LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE TITLE

XD4F21

STATE FORM